Map ID MAP FINDINGS

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

LOWER ECORSE CREEK DUMP (Continued)

1000865875

MI INVENTORY

Violation Status: No violations found

ROD:

Full-text of USEPA Record of Decision(s) is available from EDR.

PRP:

PRP name: **BASF**

BASF

CITY OF WYANDOTTE MICHIGAN CON GAS CO MICHIGAN CON GAS CO

L67 **WALCON CORP** MI BROWNFIELDS S107135852 SE **4375 SECOND STREET** MI PART 201 N/A

< 1/8 ECORSE, MI 48229

0.044 mi.

Site 1 of 3 in cluster L 231 ft.

Actual: **BROWNFIELDS:**

584 ft. Facility ID: Not reported

Region: Focus Map:

Status: Not reported Not reported Properry Use: BEA: No

82001654 Ernie Id Number:

PART 201:

82001654 Facility ID:

Facility Status: Interim Response conducted - No further activities anticipated

Source: Miscellaneous Metal Work

SAM Score:

SAM Score Date: 05/04/2004 Not reported Township: Range: Not reported Section: Not reported Quarter: Not reported Quarter/Quarter: Not reported Not reported Pollutants:

INVENTORY:

Bea Number: Not reported Township: Ecorse District: Southeast MI Data Source: Part 201 Latitude: 42.24363 -83.14983 Longitude:

Map ID MAP FINDINGS

Direction Distance

Elevation Site Database(s) EPA ID Number

L68 WALCON PROPERTY US BROWNFIELDS 1016350954
SE 4375 SECOND STREET FINDS N/A

< 1/8 ECORSE, MI 48229

0.044 mi.

231 ft. Site 2 of 3 in cluster L

Actual: US BROWNFIELDS: 584 ft. Property Name:

584 ft.Property Name:WALCON PROPERTYFocus Map:Recipient Name:Wayne County Brownfield Redevelopment Authority

rocus map:

Grant Type: Assessment
Property Number: Not reported
Parcel size: 4.3
Latitude: 42.244473
Longitude: -83.149722

HCM Label: Address Matching-House Number

Map Scale: 100000

Point of Reference: Entrance Point of a Facility or Station

Highlights: Not reported

Datum: North American Datum of 1983

 Acres Property ID:
 12413

 IC Data Access:
 Not reported

 Start Date:
 03/31/2000 00:00:00

Redev Completition Date: Not reported

Completed Date: 03/31/2000 00:00:00

Acres Cleaned Up: Not reported Cleanup Funding: Not reported Cleanup Funding Source: Not reported Assessment Funding: Not reported Assessment Funding Source: Not reported Redevelopment Funding: Not reported Redev. Funding Source: Not reported Redev. Funding Entity Name: Not reported Redevelopment Start Date: Not reported Assessment Funding Entity: Not reported Cleanup Funding Entity: Not reported

Grant Type: N/A

Accomplishment Type: Phase I Environmental Assessment

Accomplishment Count: 0

Cooperative Agreement Number: 98599701

Start Date: 03/31/2000 00:00:00
Ownership Entity: Not reported

Completion Date: 03/31/2000 00:00:00

Current Owner: Not reported Did Owner Change: Not reported

Cleanup Required: Y

Video Available: Not reported Photo Available: Not reported Institutional Controls Required: Not reported IC Category Proprietary Controls: Not reported IC Cat. Info. Devices: Not reported IC Cat. Gov. Controls: Not reported IC Cat. Enforcement Permit Tools: Not reported IC in place date: Not reported

IC in place:

State/tribal program date:
State/tribal program ID:
State/tribal NFA date:
Not reported
Not reported
Air contaminated:
Not reported
Not reported
Not reported
Not reported
Not reported

EDR ID Number

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

WALCON PROPERTY (Continued)

1016350954

Asbestos found: Not reported Not reported Asbestos cleaned: Not reported Controled substance found: Controled substance cleaned: Not reported Drinking water affected: Not reported Drinking water cleaned: Not reported Groundwater affected: Not reported Groundwater cleaned: Not reported Not reported Lead contaminant found: Lead cleaned up: Not reported No media affected: Not reported Unknown media affected: Not reported Other cleaned up: Not reported Other metals found: Not reported Other metals cleaned: Not reported Other contaminants found: Not reported Not reported Other contams found description: PAHs found: Not reported PAHs cleaned up: Not reported PCBs found: Not reported PCBs cleaned up: Not reported Petro products found: Not reported Petro products cleaned: Not reported Sediments found: Not reported Sediments cleaned: Not reported Soil affected: Not reported Soil cleaned up: Not reported Surface water cleaned: Not reported VOCs found: Not reported VOCs cleaned: Not reported Cleanup other description: Not reported Num. of cleanup and re-dev. jobs: Not reported Past use greenspace acreage: Not reported Past use residential acreage: Not reported Surface Water: Not reported Not reported Past use commercial acreage: Past use industrial acreage: Not reported Future use greenspace acreage: Not reported Future use residential acreage: Not reported Future use commercial acreage: Not reported Not reported Future use industrial acreage: Not reported Greenspace acreage and type: Superfund Fed. landowner flag: Not reported Arsenic cleaned up: Not reported Cadmium cleaned up: Not reported Chromium cleaned up: Not reported Copper cleaned up: Not reported Iron cleaned up: Not reported mercury cleaned up: Not reported Nickel Cleaned Up: Not reported No clean up: Not reported Pesticides cleaned up: Not reported Selenium cleaned up: Not reported Not reported SVOCs cleaned up: Unknown clean up: Not reported Arsenic contaminant found: Not reported Cadmium contaminant found: Not reported

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WALCON PROPERTY (Continued)

1016350954

Chromium contaminant found: Not reported Not reported Copper contaminant found: Not reported Iron contaminant found: Mercury contaminant found: Not reported Nickel contaminant found: Not reported Not reported No contaminant found: Not reported Pesticides contaminant found: Selenium contaminant found: Not reported SVOCs contaminant found: Not reported Unknown contaminant found: Not reported Future Use: Multistory Not reported Media affected Bluiding Material: Not reported Media affected indoor air: Not reported Building material media cleaned up: Not reported Indoor air media cleaned up: Not reported Unknown media cleaned up: Not reported Past Use: Multistory Not reported Property Description: Industrial Below Poverty Number: 1142 Below Poverty Percent: 30.5% Meidan Income: 5570 Meidan Income Number: 1941 51.9% Meidan Income Percent: Vacant Housing Number: 467 Vacant Housing Percent: 25.1% Unemployed Number: 413 **Unemployed Percent:** 11.0%

FINDS:

Registry ID: 110039529551

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to

electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

L69 WALCON CORP. RCRA NonGen / NLR 1000179731

SE 4375-2ND ST. **ECORSE, MI 48229** < 1/8

0.044 mi.

Site 3 of 3 in cluster L 231 ft. RCRA NonGen / NLR: Actual:

584 ft. Date form received by agency: 12/31/2001 Facility name: WALCON CORP Focus Map: Facility address: 4375 2ND ST

> ECORSE, MI 48229 EPA ID: MID038601746

NOT OBTAINED NOT OBTAINED Contact:

Contact address: 4375 2ND ST

ECORSE, MI 48229

US Contact country:

MID038601746

FTTS

HIST FTTS

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

WALCON CORP. (Continued) 1000179731

Contact telephone: 000-000-0000 Contact email: Not reported

EPA Region: 05

Land type: Other land type Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address:

Owner/operator country:

Owner/operator telephone:

Owner/operator email:

Owner/operator fax:

Owner/operator extension:

Not reported

Not reported

Not reported

Not reported

Not reported

Owner/operator extension: Not reported Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2002
Owner/Op end date: Not reported

Owner/operator name: NO ACTIVE O/OP AS NOT GENERATING WASTE

Owner/operator address: Not reported

Not reported

Not reported

Owner/operator country: Not reported Owner/operator telephone: Not reported Owner/operator email: Not reported Owner/operator fax: Not reported Owner/operator extension: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 01/01/2002

Handler Activities Summary:

Owner/Op end date:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: Nο Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: Nο Used oil transporter: No

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET,

Map ID MAP FINDINGS

Direction Distance Elevation

evation Site Database(s) EPA ID Number

WALCON CORP. (Continued)

1000179731

EDR ID Number

WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:

Date form received by agency: 09/07/1983
Site name: WALCON CORP
Classification: Small Quantity Generator

Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 05/11/1992
Date achieved compliance: 10/26/1992
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/11/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/11/1992
Date achieved compliance: 10/26/1992
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/11/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 05/02/2001

Evaluation: FOCUSED COMPLIANCE INSPECTION

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/05/1992

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number**

WALCON CORP. (Continued)

1000179731

EDR ID Number

Area of violation: Generators - General

10/26/1992 Date achieved compliance: Evaluation lead agency: State

Evaluation date: 05/05/1992

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: LDR - General Date achieved compliance: 10/26/1992 Evaluation lead agency: State

FTTS INSP:

19880331MI013 1 Inspection Number:

Region: 05

Inspection Date: 03/31/88 Inspector: COOPER Violation occurred: No

Section 6 PCB State Conducted Investigation Type:

Investigation Reason: Neutral Scheme, State

Legislation Code: **TSCA** Facility Function: Manufacturer

HIST FTTS INSP:

Inspection Number: 19880331MI013 1

Region: 05

Inspection Date: Not reported COOPER Inspector:

Violation occurred: No

Section 6 PCB State Conducted Investigation Type:

Investigation Reason: Neutral Scheme, State

Legislation Code: TSCA Facility Function: Manufacturer

70 **WOODWARD DETROIT CVS LLC** SE

3859 W JEFFERSON AVE

ECORSE, MI 48229 < 1/8

0.047 mi. 249 ft.

Actual: RCRA NonGen / NLR:

580 ft. Date form received by agency: 06/19/2017

WOODWARD DETROIT CVS LLC Facility name: Focus Map: Facility address: 3859 W JEFFERSON AVE

ECORSE, MI 48229

EPA ID: MIK199618737 Mailing address: 1 CVS DRIVE

WOONSOCKET, RI 02895

Contact: DIANNE L DURAND

Contact address: Not reported Not reported

Not reported Contact country: Contact telephone: 401-770-3315

DIANNE.DURAND@CVSHEALTH.COM Contact email:

EPA Region:

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste 1014954800

MIK199618737

RCRA NonGen / NLR